

## <u>PALM INTRANET</u>

Day: Friday Date: 6/10/2005

Time: 17:52:29

## **Inventor Name Search Result**

Your Search was:

Last Name = WANG First Name = JIANHUA

Application#	Patent#	Status	Date Filed	Title	Inventor Name 27
60552816	Not Issued	159	03/13/2004	MULTIMODE OPTICAL FIBER COUPLER AND FABRICATION METHOD	WANG, JIANHUA
60552815	Not Issued	159	03/13/2004	MULTIMODE OPTICAL FIBER COUPLER AND FABRICATION METHOD	WANG, JIANHUA
60552814	Not Issued	159	03/13/2004	MULTIMODE OPTICAL FIBER COUPLER AND FABRICATION METHOD	WANG, JIANHUA
60552813	Not Issued	159	03/13/2004	MULTIMODE OPTICAL FIBER COUPLER AND FABRICATION METHOD	WANG, JIANHUA
60538931	Not Issued	159	01/24/2004	OPTICAL FILTER ASSEMBLY	WANG, JIANHUA
11079687	Not Issued	030	03/12/2005	MULTIMODE OPTICAL FIBER COUPLER AND FABRICATION METHOD	WANG, JIANHUA
<u>11079686</u>	Not Issued	030	03/12/2005	MULTIMODE OPTICAL FIBER COUPLER AND FABRICATION METHOD	WANG, JIANHUA
11079685	Not Issued	030	03/12/2005	MULTIMODE OPTICAL FIBER COUPLER AND FABRICATION METHOD	WANG, JIANHUA
11079683	Not Issued	030	03/12/2005	MULTIMODE OPTICAL FIBER COUPLER AND FABRICATION METHOD	WANG, JIANHUA
11041688	Not Issued	030	01/23/2005	OPTICAL FILTER ASSEMBLY AND METHOD	WANG, JIANHUA
11007631	Not Issued	030	12/08/2004	SUN VISOR ASSEMBLY	WANG, JIANHUA
10941249	Not Issued	030	09/15/2004	TEAR DYNAMICS MEASURED WITH OPTICAL COHERENCE TOMOGRAPHY	WANG, JIANHUA

10933867	Not Issued	020	09/03/2004	CARBAZOLE DERIVATIVE AND ITS USE IN ELECTROLUMINESCENT DEVICES	WANG, JIANHUA
10851553	Not Issued	030	05/21/2004	COMPACT HIGH-STABILITY OPTICAL SWITCHES	WANG, JIANHUA
10802126	Not Issued	094	03/16/2004	COMPACT HIGH-STABILITY OPTICAL SWITCHES	WANG, JIANHUA
10718355	Not Issued	030	11/18/2003	OPTICAL MODULE PACKAGE	WANG, JIANHUA
10408073	6904223	150	04/04/2003	TILTED-TRANSLATION VARIABLE OPTICAL ATTENUATOR	WANG, JIANHUA
10314537	6863778	150	12/09/2002	SEPARATION OF TERTIARY BUTYL ALCOHOL FROM DIISOBUTYLENE	WANG, JIANHUA
10259091	Not Issued	161	09/26/2002	BROADBAND POLARIZATION INSENSITIVE OPTICAL ISOLATORS	WANG, JIANHUA
10184553	6714716	150	06/28/2002	VARIABLE OPTICAL ATTENUATOR	WANG, JIANHUA
09812617	6721474	150	03/19/2001	FIBER OPTIC SWITCH USING GALVANOMETER-DRIVEN X-Y SCANNING	WANG, JIANHUA
09812358	6580868	150	03/19/2001	HIGH-RESOLUTION VARIABLE OPTICAL ATTENUATOR WITH MECHANICAL ADJUSTMENT	WANG, JIANHUA
09599138	Not Issued	041	06/22/2000	APPARATUS, AND ASSOCIATED METHOD, FOR INTEGRATING OPERATION OF PACKET RADIO COMMUNICATION SYSTEMS	WANG, JIANHUA
09599136	Not Issued	092	06/22/2000	APPARATUS, AND ASSOCIATED METHOD, FOR INTEGRATING OPERATION OF PACKET RADIO COMMUNICATION SYSTEMS	WANG, JIANHUA
09081212	5956865	250	05/20/1998	PROCESS FOR DRYING HERBS	WANG, JIANHUA (LINDA)
08618096	5792361	250	03/19/1996	METHOD FOR TREATMENT OF AN AQUEOUS WASTE MATERIAL	WANG, JIANHUA

Inventor Search Completed: No Records to Display.

**Last Name** 

First Name

		F	
Search Another: Inventor	WANG	JIANHUA	Search
	<del></del>	**************************************	

To go back use Back button on your browser toolbar.

Back to PALM | ASSIGNMENT | OASIS | Home page

	Туре	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	34	"4859825" "5189724" "5758004" "5838871" "6014490" "6118914" "6195494" "6321021" "6334020" "6377735" "6415092" "6424784"	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/10 17:36
2	BRS	L3	3	2 and (tube\$1 ferrule\$1 condit\$1) same (mov\$4 slid\$3) same (fiber\$1 fibre\$1 waveguide\$1)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/10 17:38
3	BRS	L2	16	"6014490" "6118914" "6195494" "6321021"	10(20)16.	2005/06/10 17:40
4	BRS	L4	7	2 and (connectors)	US- PGPUB; USPAT; EPO; JPO; DERWEN	2005/06/10 17:41

	Comments	Error Definition	Err
<u> </u>			ors
1	)		
2	·		
3			
4			

	Туре	Hits	Search Text
1	BRS	343	((tubes ferrules conduits) ((second outer) adj1 (tube ferrule condit))) near5 (mov\$4 slid\$3) near7 (fiber\$1 fibre\$1 waveguide\$1)
2	BRS	29	<pre>(tube\$1 ferrule\$1 condit\$1) near5 (mov\$4 slid\$3) near7 (fiber\$1 fibre\$1 waveguide\$1) same (thermal\$3 near3 expan\$5)</pre>
3	BRS	3	S1 and S2
4	BRS	1953	(tube\$1 ferrule\$1 condit\$1) near5 (mov\$4 slid\$3) near7 (fiber\$1 fibre\$1 waveguide\$1)
5	BRS	313	S1 and S4
6	BRS	2877	connectors same (fiber\$1 fibre\$1 waveguide\$1) same hous\$4
7	BRS	14	S5 and S6
8	BRS	14	S7 not S3
9	BRS	2302	<pre>(tube\$1 ferrule\$1 condit\$2) near5 (mov\$4 slid\$3 expand\$3) near7 (fiber\$1 fibre\$1 waveguide\$1)</pre>
10	BRS	106	S6 and S9
11	BRS	33514	((tubes ferrules conduits) ((second outer) adj1 (tube ferrule condit))) same (fiber\$1 fibre\$1 waveguide\$1)
12	BRS	87	S10 and S11
13	BRS	4650	(tub\$3 ferrule\$1 conduit\$2) near4 thermal\$3 near3 expan\$5
14	BRS	2	S12 and S13
15	BRS	1801	<pre>(tube\$1 ferrule\$1 condit\$2) near5 (mov\$4 expand\$3) near7 (fiber\$1 fibre\$1 waveguide\$1)</pre>
16	BRS	824	S15 and S11
17	BRS	5743	(tub\$3 ferrule\$1 conduit\$2) near5 thermal\$3 near3 expan\$5
18	BRS	72	S6 and S16

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 18:10		
2	US-PGPUB; USPAT; EPO; JPO; DERWENT			
3	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 17:21		
4	US-PGPUB; USPAT; EPO; JPO; DERWENT			
5	US-PGPUB; USPAT; EPO; JPO; DERWENT			
6	US-PGPUB; USPAT; EPO; JPO; DERWENT			
7	US-PGPUB; USPAT; EPO; JPO; DERWENT			
8	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 12:11		
9	US-PGPUB; USPAT; EPO; JPO; DERWENT			
10	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 18:09		
11	US-PGPUB; USPAT; EPO; JPO; DERWENT			
12	US-PGPUB; USPAT; EPO; JPO; DERWENT			
13	US-PGPUB; USPAT; EPO; JPO; DERWENT			
14	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 18:13	·	
15	US-PGPUB; USPAT; EPO; JPO; DERWENT	1		
16	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 18:20		
17	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 18:19		
18	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 18:21		

	Errors	Ref #
1		S1
2		S2
3		S3
4		S4
5		S5
6		S6
7		S7
8		S8
9		S9
10		S10
11		S11
12		S12
13		S13
14		S14
15		S15
16		S16
17		S17
18		S18

	Туре	Hits	Search Text
19	BRS	1428	<pre>(tube\$1 ferrule\$1 condit\$2) near5 (mov\$4) near7 (fiber\$1 fibre\$1 waveguide\$1)</pre>
20	BRS	57	S18 and S19
21	BRS	49	S20 not S8
22	BRS	2	(tubes ferrules) near3 (mov\$4) near3 therm\$4 near3 expans\$4 same (fiber\$1 fibre\$1 waveguide\$1) same (hous\$4 connect\$4)
23	BRS	3	(tub\$4 ferrule\$1) near5 (mov\$4) near5 therm\$4 near3 expans\$4 same (fiber\$1 fibre\$1 waveguide\$1) same (hous\$4 connect\$4)
24	BRS	102	(tub\$4 ferrule\$1) near5 therm\$4 near3 expans\$4 near5 (mov\$4)
25	BRS	О	S6 and S24
26	BRS	5	S24 and connector\$1 and (fiber\$1 fibre\$1 waveguide\$1)
27	BRS	2	"5179608".pn.
28	BRS	1	S27 and S24
29	BRS	1	S28 and (ferrul\$4 near5 mov\$6)
30	BRS	1	S27 and (tub\$4 ferrule\$1) near5 therm\$4 near3 expans\$4 near7 (mov\$4)
31	BRS	3	"6517253".pn.
32	BRS	344	((tubes ferrules conduits) ((second outer) adj1 (tube ferrule condit))) near5 (mov\$4 slid\$3) near7 (fiber\$1 fibre\$1 waveguide\$1)
33	BRS	29	(tube\$1 ferrule\$1 condit\$1) near5 (mov\$4 slid\$3) near7 (fiber\$1 fibre\$1 waveguide\$1) same (thermal\$3 near3 expan\$5)
34	BRS	3	S32 and S33
35	BRS	1956	<pre>(tube\$1 ferrule\$1 condit\$1) near5 (mov\$4 slid\$3) near7 (fiber\$1 fibre\$1 waveguide\$1)</pre>

	DBs	Time Stamp	Comments	Error Definition
19	US-PGPUB; USPAT; EPO; JPO; DERWENT			
20	US-PGPUB; USPAT; EPO; JPO; DERWENT			
21	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 18:22		·
22	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 19:13		
23	US-PGPUB; USPAT; EPO; JPO; DERWENT			
24	US-PGPUB; USPAT; EPO; JPO; DERWENT			
25	US-PGPUB; USPAT; EPO; JPO; DERWENT			
26	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 19:24		
27	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/08 19:25		
28	US-PGPUB; USPAT; EPO; JPO; DERWENT			
29	US-PGPUB; USPAT; EPO; JPO; DERWENT			
30	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 12:09		
31	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 17:36	·	
32	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 12:11		·
33	US-PGPUB; USPAT; EPO; JPO; DERWENT			
34	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 12:13		
35	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 17:37		

	Errors	Ref #
19		S19
20		S20
21		S21
22		S22
23		S23
24		S24
25		S25
26		S26
27		S27
28		S28
29		S29
30		S30
31		S31
32		S32
33		S33
34 .		S34
35		S35

	Туре	Hits	Search Text
36	BRS	314	S32 and S35
37	BRS	2879	connectors same (fiber\$1 fibre\$1 waveguide\$1) same hous\$4
38	BRS	14	S36 and S37
39	BRS	14	S38 not S34
40	BRS	1	S31 and connectors same (fiber\$1 fibre\$1 waveguide\$1) same hous\$4
41	BRS	1	S31 and S35 and S36
42	BRS	1	S31 and (tube\$1 ferrule\$1 condit\$1 fiber\$1 fibre\$1 waveguide\$1) near12 (mov\$4 slid\$3 'with respect')
43	BRS	2	S31 and (light wavelength\$1 sourc\$3 laser diod\$3 device\$2 opto\$6 optic\$4 beam\$4)
44	BRS	o	S31 and (input\$4 output\$4)
45	BRS	2	S31 and (input\$4 out\$6)
46	BRS	2	S45 and connect\$5
47	BRS	2	\$31 and (connect\$5 fast\$5 coup\$5 lock\$4)
48	BRS	2	S31 and (connect\$5 fast\$5 coup\$5 lock\$4 interfac\$4 hock\$4 hok\$4)
49	BRS	2	S31 and (fiber\$1 waveguide\$1)
50	BRS	3	"6517253".pn.
51	BRS	1	S50 and (tube\$1 ferrule\$1 condit\$1. fiber\$1 fibre\$1 waveguide\$1 out\$5 inn\$3) near12 (mov\$4 slid\$3 'with respect')
52	BRS	1	S50 and (tube\$1 ferrule\$1 condit\$1 fiber\$1 fibre\$1 waveguide\$1 out\$5 inn\$3) near12 (mov\$4 slid\$3 'with respect') same (fiber\$1 cabl\$2 waveguide\$1)

	DBs	Time Stan	- 1	Comments	Error Definition
36	US-PGPUB; USPAT; EPO; JPO; DERWENT				
37	US-PGPUB; USPAT; EPO; JPO; DERWENT				
38	US-PGPUB; USPAT; EPO; JPO; DERWENT				
39	US-PGPUB; USPAT; EPO; JPO; DERWENT				
40	US-PGPUB; USPAT; EPO; JPO; DERWENT				
41	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1	2:13		
42	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1	4:14		*
43	US-PGPUB; USPAT; EPO; JPO; DERWENT				
44	US-PGPUB; USPAT; EPO; JPO; DERWENT				
45	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1	2:51		
46	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1:	2:57		
47	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1	2:59		
48	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1	3:11		
49	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1	3:11		
50	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1	5:55		
51	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1	4:17		
52	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 1	4:19		

	Errors	Ref #
36		S36
37		S37
38		S38
39		S39
40		S40
41		S41
42		S42
43	·	S43
44		S44
45	,	S45
46		S46
47		S47
48		S48
49		S49
50		S50
51		S51
52		S52

	Туре	Hits	Search Text
53	BRS	1	S50 and (tube\$1 ferrule\$1 condit\$1 fiber\$1 fibre\$1 waveguide\$1 out\$5 inn\$3) same (mov\$4 slid\$3 'with respect') same (fiber\$1 cabl\$2 waveguide\$1)
54	BRS	3	"6517253".pn.
55	BRS	2	S54 and (fus\$4 coup\$4)
56	BRS	o	S50 and (split\$4 isolat\$4 circulat\$4 attenuat\$5 switch\$4 wavelength\$3 multiplex\$5 demultipl\$5 wdm\$2)
57	BRS	1	S50 and (divid\$4)

	DBs	Time Stamp	Comments	Error Definition
	US-PGPUB; USPAT; EPO; JPO; DERWENT			
	US-PGPUB; USPAT; EPO; JPO; DERWENT			
55	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 15:58		
İ	US-PGPUB; USPAT; EPO; JPO; DERWENT			
57	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/06/10 16:00		

	Errors	Ref #
53		S53
54		S54
55		S55
56		S56
57		S57